



# HYDRO MINERAL

## TECHNICAL DATA SHEET

### CLEANER RTF Roofs | Terraces | Facades

#### PROCESS INTRODUCTION :

Hydro-Mineral CLEANER RTF is a powerful cleaner for porous mineral materials. Spray the surface area to be treated and its action is immediate. Rinse with a high-pressure washer (set at the minimum level).

The same result can be achieved by leaving it work with rain as rinsing with water. A period of 6 months is usually necessary to see the final result; in this case, it is necessary to first remove the patches of mosses.

Hydro-Mineral CLEANER RTF does not alter and does not damage the materials for which it is intended.



#### DOMAIN OF IMPLEMENTATION :



Outside



Rinsing by  
rain water



Pressure  
washer

Hydro-Mineral CLEANER RTF can be used on all porous mineral surfaces.



#### Limitations of use :

DO NOT APPLY CLEANER RTF Hydro-Minéral RTF on any other material such as glass, aluminium, paint, varnish, PVC, etc.



**PACKAGING :** Plastic containers 20 L and 5 L.

\* Dangerous - Respect safety precautions.

The information contained in this leaflet is intended to help users. It is from the result of tests carried out objectively in our laboratories. It is up to the users of our products to decide if the products are suitable for the job they want to do.

In doing so, Hydro-Mineral do not assume responsibility and expressly disclaim liability for loss, damage or expense arising out of or in any way connected with the handling, storage, use or disposal of the product.

Hydro-Minéral International (HMI) : Tél : +33(0)9.87.53.02.60 Mail : hmi@hydro-mineral.net  
73000 CHAMBERY-Savoie Mont-Blanc- FRANCE - Siret : 840 843 155 00010 - APE 4675 Z



# HYDRO MINERAL

## IMPLEMENTATION SHEET

### CLEANER RTF Roofs | Terraces | Facades

#### APPLICATION :



Spray



Protective Sheet



Adhesive Tape

**On roofs :** Apply Hydro-Mineral CLEANER RTF with a spray;  
For immediate results, leave it work for 30 minutes, then rinse with a high-pressure washer (between 100 and 150 bar). The same result can be achieved by leaving it work with rain as rinsing with water. 6 months are usually necessary to see the final result; in this case, it is necessary to first remove any patches of moss.

**On Facades and Terraces :** Apply Hydro-Mineral CLEANER RTF with a spray; leave it work for 30 minutes, then rinse with a high-pressure washer (set at the minimum level for rendered facades).

**AVERAGE CONSUMPTION :** 1 Litre = 8 m<sup>2</sup> (7 L/m<sup>2</sup> on facade and fiber cement)

#### CONDITIONS AND PRECAUTIONS OF APPLICATION :

|                 |         |          |
|-----------------|---------|----------|
| Air temperature | 3°C Min | 30°C Max |
|-----------------|---------|----------|

MINERALIZER RTF is ready to use. Do not mix it with another product. Do not dilute.

**It is essential to protect all the materials which are not to undergo this treatment :** glass surfaces, door frames and conservatories in aluminium or PVC, paint, wood frames, vehicles, nearby vegetation etc...

Do not apply in direct sunlight. Do not apply in frosty weather or when there is a risk of frosting in the hours which follow the application. Do not use the spray in high winds.

**Shake the container well before use.**



Gutters



Openings



Verandas

**EQUIPMENT CLEANING:** Clean the equipment with water, rinsing thoroughly, do not leave any product in the spray. Recycle or dispose of the packaging in accordance with the legislation in force.

#### PHYSICAL AND CHEMICAL PROPERTIES :

**ASPECT :** Liquid    **COLOUR :** Colourless    **ODOUR :** None    **SOLUBILITY :** Total

**DANGER AND SAFETY INFORMATION :** **H314:** Causes severe skin burns and eye damage. **P101:** If medical advice is needed, have product container or label at hand. **P102:** Keep out of reach of children. **P103:** Read label before use. **P260:** Do not breathe vapours. **P280:** Wear protective gloves / protective clothing / eye protection / face protection. **P301+P330+P331:** IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. **P303+P361+P353:** IF ON SKIN (or hair) Take off immediately all contaminated clothing Rinse skin with water/shower.. **P304+P340:** IF INHALED : Remove person to fresh air and keep comfortable for breathing.. **P305+P351+P338:** IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do – continue rinsing. **P363:** Wash contaminated clothing before reuse. **P312:** Call a ANTI POISON CENTER or a doctor in case you feel unwell. **P501:** Dispose of contents / container to a disposal facility in accordance with local regulations.

#### PERSONAL PROTECTION :



Safety glasses



Respiratory protection



Gloves



Rubber boots




Coveralls

The information contained in this leaflet is intended to help users. It is up to the users of our products to decide if the products are suitable for the job they want to do. In doing so, Hydro-Mineral do not assume responsibility and expressly disclaim liability for loss, damage or expense arising out of or in any way connected with the handling, storage, use or disposal of the product.

Hydro-Minéral International (HMI) : Tél : +33(0)9.87.53.02.60 Mail : hmi@hydro-mineral.net  
73000 CHAMBERY-Savoie Mont-Blanc- FRANCE - Siret : 840 843 155 00010 – APE 4675 Z



View the implementation video



Scan code